

**University of Tennessee Knoxville**
**Job Hazard Analysis and Personal Protective Equipment Assessment**

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

**Paint Conditioner/Shaker**

Task	Hazard	Cause	Prevention
General Use	Foot Injury	Drop object on foot	Safety shoes
	Electric Shock	Improper operation and maintenance, improper grounding	Manufacturer's instructions strictly followed, proper grounding
	Eye Injury	Paint splash	Goggles, face shield, apron, gloves, proper operation of shaker
	Hand Injury	Point of Operation, rotating parts	Situational awareness

PPE Required:

- Apron
- Face Shield
- Gloves
- Goggles
- Safety Shoes/Boots

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

*April W. Case*

EHS Team Leader General Safety

Date 12/4/2017