

University of Tennessee Knoxville**Job Hazard Analysis and Personal Protective Equipment Assessment**

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Pneumatic Nail Gun

Task	Hazard	Cause	Prevention
General Use	Eye Injury	Projectiles, residual air pressure, flying debris	Safety glasses with side shields, situational awareness
	Trauma	Air Pressure, ejection of tool	Situational awareness, tool retainer
	Noise	Equipment Operation	Use hearing protection
	Foot Injury	Drop object on foot	Safety shoes
	Hand Injury	Point of Operation	Situational awareness

PPE Required:

- Safety Glasses with side shields
- Hearing Protection
- Safety Shoes/ Boots

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017