

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:
Steam Cleaner

Task	Hazard	Cause	Prevention
General Use	Trauma	Flying debris, contact with steam	Rotating parts, burns, situational awareness, protective clothing
	Hand Injury	Flying Debris, Contact with steam	Situational awareness, gloves
	Eye Injury	Flying debris	Full face shield
	Fire	Smoking, sparks	No smoking or exposure to sparks or open flame during fueling. Appropriate placed fire extinguisher

PPE Required:

- Full Face Shield
- Gloves
- Apron

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017