

University of Tennessee Knoxville

Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task

Hazard Analysis:

Valves (Operating)

Task	Hazard	Cause	Prevention
General Use	Eye Injury	Projectiles, fumes, dusts	Safety glasses w/side shields or goggles (for chemical piping), face shield (if needed)
	Trauma	Projectiles, impact, burns	Situational awareness, gloves, protective clothing (long sleeves/pants)
	Foot Injury	Dropped object on foot	Wear safety shoes

PPE Required:

- Safety Glasses w/side shields or Goggles
- Safety Shoes/boots
- Gloves protective Clothing (long sleeves/pants)
- Face Shield (if needed)

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case
EHS Team Leader General Safety

Date 12/4/2017