



# Warning



## Welding

- **Fumes and Gases may cause**
  - **irritation of the eyes, nose, and throat**
  - **chest pain/pulmonary edema**
  - **chronic lung diseases/lung cancer**
  - **metal fume fever/lead poisoning**
- **Polyester and other man-made fibers may melt and cause severe burns if struck by welding sparks**
- **May result in asphyxiation in confined spaces**

*This posting is required by the Tennessee Occupational Safety and Health Administration*