

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Jack Stands, Manual

Task	Hazard	Cause	Prevention
General Use	Foot Injury	Improper placement of load	Situational awareness, wear safety shoes
	Trauma	Overloading vehicle stand beyond rated capacity	Follow manufacturer's instructions. Ensure that rated load is legibly and permanently marked in a prominent location on vehicle stand, and rated load capacity is not exceeded.

PPE Required:

- Safety Shoes/Boots

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017