

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Hydraulic Press

Task	Hazard	Cause	Prevention
General Use	Eye Injury	Projectiles	Safety glasses with side shield or appropriate safety goggles
	Trauma	Projectiles, moving parts, point of operation, pinch points, flying items	Situational awareness, PPE, protective clothing, machine guards
	Foot Injury	Drop object on foot	Wear safety shoes
	Hand Injury	Point of operation, pinch points, moving parts, flying items.	Gloves, machine guards, situational awareness
	Head Protection	Projectiles	Face Shield (as necessary)

PPE Required:

- Protective Clothing (optional)
- Safety Shoes/Boots
- Goggles/Safety Glasses w/side shield
- Gloves
- Face shield (as necessary)

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017